

There is no audio output when connected to OS3.0 iPod/iPhone

Problem

When Bluetooth and Dock Connector are connected at the same time, the audio may not be output from the Receiver.

Cause

Bluetooth A2DP Profile is equipped with iPod OS3.0. iPod transfers the audio from either Bluetooth or Dock Connector to the Receiver. Depending on the iPod spec, the setting may be automatically switched.

Affected models


iPhone3GS, iPhone 3G (Upgrade to OS3.0),
iPod Touch 2nd Generation (Upgrade to OS3.0)

Method of confirmation


If there is no audio output during iPod playback, make sure that the iPod settings are configured as indicated below.

* If the Receiver is USB-iPod source -> Dock Connector

* If the Receiver is Bluetooth source -> Bluetooth Device Name of Receiver (JVC Unit etc.)



When the Receiver is USB-iPod source, iPod must indicate [Dock Connector].



When the Receiver is Bluetooth source, iPod must indicate [Bluetooth Device Name]*.
* eg. [JVC Unit]



In case that the Receiver source does not match the indication on the iPod screen, press this icon and select the correct outputting device (Audio Device).